


Three-phase motor with 2 speeds
with 2 separate windings
for star-delta starting in each winding

Conn. diagram
KP 0005



All terminals to the pole-changing switch with built-in star/delta-starting.

Attention: During motor operation, the delta connection of the winding which is not at voltage level, must be open!!!

			Datum	27.12.2004	
			Bearb	Kresse	
			Gepr		
			Norm		
					
			Elektromotorenwerk Wernigerode		
			Zeichnungs-Nr.		
			KP 0005 e		
01					
Zust.	Mitteilung	Datum	Name		